



Reverification note for Site Wind Conditions Assessment, Hesselø South OWF

Kontor/afdeling
Havvind

Dato
29-10-2024

This note explains why the delivery ID 2109 is not necessary.

The site wind conditions assessments ID 1105, ID 3105 and ID 4105 are based on only 8 months of data collection and datasets from nearby locations, which was required to meet the deadline in the time schedule. This means that a reverification note based on the complete data collection (12 months) is needed for those wind farm areas (ID 1109, 3109 and 4108). However, the Hesselø South Site Wind conditions assessment (ID 2105) is based on a 12 month data collection and datasets from nearby locations. Therefore a reverification note (ID 2109) is not needed for Hesselø South wind farm area.

Energistyrelsen

Carsten Niebuhrs Gade 43
1577 København V

Niels Bohrs Vej 8
6700 Esbjerg

T: +45 3392 6700
E: ens@ens.dk

www.ens.dk